

Irvington Sidewalk Survey 2026
4/14/2026



King Carter Road

To Winstead

Irvington Road
to Kilmarnock

Steamboat Road

Irvington Road
to White Stone

- Irvington Maintained
- VDOT Maintained
- All Curbs Maintained
By VDOT

2026 Irvington Sidewalk Survey
4/14/24

Item 1 – Sidewalk slab
sinking about 1 Inch behind
manhole at Museum at 156
King Carter Drive.

[VDOT](#)



Item 2: Broken Slab next to
entrance of 4303 Irvington
Road.

[Town of Irvington](#)



Item 3: Broken Slab next to
entrance of 4323 Irvington
Road (Red Fish).

[Town of Irvington](#)



2026 Irvington Sidewalk Survey
4/14/24

Item 4 – Sidewalk has Deteriorated in front of 4395 Irvington Road (ETB Consulting)

[Town of Irvington](#)



Item 5 – Start of deterioration of curb in front of Ramsey and Bugg at 4421 Irvington Road (From 2024)


VDOT



2026 Irvington Sidewalk Survey
4/14/24

Item 6 – Deterioration of curb in several locations between gas station at 4525 Irvington Road and the Post Office (From 2024)

VDOT



Item 7: Steamboat Road, South side of Seafood Lane Entrance. Slab cracked and sunken above drainage invert.

[Town of Irvington](#)



Item 8 – Apron to Gaskins Landing
driveway needs replacing

[Town of Irvington](#)



Item 9 – 359 Steamboat Road Driveway cut
in front of a house, could cause tripping

[Town of Irvington](#)



Item 10 – 242 Steamboat Road. Sidewalk heaving and encroachment of soil onto sidewalk

[Town of Irvington and Owners](#)



Item 11 – 45 Steamboat Road. Sidewalk encroachment by lawn.


[Owners](#)



2026 Irvington Sidewalk Survey
4/14/24

Item 12 – 200 Steamboat Road. Yard
encroachment onto sidewalk

Owners



Item 13: Sunken Slab between 26
Steamboat Road and 4524 Irvington Road in
front of No Parking Sign

Town of Irvington

